





MISSED APPROACH:
By passing **NDB "ON"** climb straight ahead to **1500m**.

TRANSITION LEVEL 2400

TRANSITION ALTITUDE 1800

TRANSITION ALTITUDE 2100 (QNH±1031hPa)



CAT of ACFT	A/B	
	OCA (H)	MDA (H)
Straight-in Approach	940 (192)	950 (202)

VIS	
CAT of ACFT	ALS Out
A/B	2200