





MISSED APPROACH:
By passing NDB "HN" climb straight ahead to ALT 1500.

TRANSITION LEVEL	2400
TRANSITION ALTITUDE	1800
TRANSITION ALTITUDE	2100 (QNH±1031hPa)



CAT of ACFT	A/B, C	
	OCA (H)	MDA (H)
Straight-in Approach	970 (231)	1000 (261)

VIS		
CAT of ACFT	FULL	ALS Out
A/B	2400m	2800m
C	3000m	3400m