





MISSED APPROACH:
By passing NDB "HN" climb
straight ahead to ALT 1500.

TRANSITION LEVEL	2400
TRANSITION ALTITUDE	1800
TRANSITION ALTITUDE	2100 (QNHz1031hPa)



CAT of ACFT	C	
	OCA (H)	MDA (H)
Straight-in Approach	970 (231)	1000 (261)
VIS		
CAT of ACFT	FULL	ALS Out
C	3000m	3400m