





MISSED APPROACH:
Climb straight ahead to **ALT 2400**
then turn left, direct to **"MU" NDB**
and Hold at **ALT 3000**.

NO TURN before MAPT



CAT of ACFT	C	
	OCA (H)	MDA (H)
Straight-in Approach	2160 (868)	2200 (908)

VIS		
CAT of ACFT	FULL	ALS Out
C	5000 m	